

IN THE SPECIFICATION

Please amend the Specification as follows:

Paragraph beginning at Page 5, Line 4:

Fig. 2 is a diagrammatic top plan view of a portion of the reflective LCD 10 array of Fig. 1, showing the layout of a plurality of mirrors 40 thereon. The mirrors 40 are in the mirror layer 14 (Fig. 1), previously discussed herein in relation to Fig. 1, and can be viewed through the protective insulating layer 28 which is over the mirror layer 14. In the view of Fig. 2 it can be seen that there are gaps 42 between the mirrors 40 wherethrough light 30 (Fig. 1) might pass. Since, in this present example, the generally square mirrors 40 are arrayed in rows and columns, the gaps 42 may be referred to as horizontal gaps 44 and vertical gaps 46, when viewed from the perspective of Fig. 2.